

FIG. 1




FIG. 2






FIG. 3




10/517337

FIG. 4



10/517337

FIG. 5



10/517337

FIG. 6




FIG. 7




FIG. 8





FIG. 9



10/517337

FIG. 10




FIG. 11




FIG. 12





FIG. 13



10/517337

FIG. 14




FIG. 15




FIG. 16




FIG. 17




FIG. 18





FIG. 19



10/517337

## FIG. 20

DATE: (hh:mm:ss)

ID CODE	MACHINE NUMBER	KIND	KEY INSERTION TIME	KEY WITHDRAWAL TIME	PERIOD OF TIME DURING WHICH THE KEY IS IN INSERTED STATE	TIME OF DISAPPEARANCE	TIME OF RECOVERY	TIME PERIOD WHERE IDENTIFICATION HAS BEEN IMPOSSIBLE	TIME AT WHICH ID ERROR HAS OCCURRED
0583208098	NO. 0002	MAIN BODY FRAME				02:38:56	03:14:28		00:35:32
0583208098	NO. 0002	MAIN BODY FRAME				03:52:39	04:01:00		00:08:21
0296738591	NO. 0134	GLASS FRAME				13:58:00	14:25:46		00:27:46
1368207964	NO. 0063	GLASS FRAME							01:32:13
9265380711	NO. 0002	KEY	02:37:45	03:14:05		00:35:20			
.....	.....	.....	.....	.....			.....	.....	.....